

NKU-08-2021 Precast Wall Panel Repairs (Existing Conditions)



Photo at Bridge, ponding conditions




Photo at Wall Panel Repair looking at Administrative Building (above)



Photo at Wall Panel Repair looking at MEP (above)



Photo at Wall Panel Repair looking at MEP (above)



Photo at Overall of Wall looking at UC Building (below)



Photo at Bridge looking at MEP (below)



Photo at Wall Panel Repair looking at Administrative Building (below)



Photo at Wall Panel Repair (below)



Photo at Wall Panel Repair (below)



Photo at Wall Panel Repair (below)



Photo at Wall Panel Repair (below)



Photo at Wall Panel Repair (below)



Photo at Overall of Wall looking at Administrative Building